Planner : ALAN DEWSNOP Priority : 3A

Drawing No : 1SGA-M2063F Clearance : YES Completed By : _______ Signature : _______

Equip No/Cat: 1SGA-C 2 Tag Request : _______ Accepted By : ______ Signature : _______

Froject ID : 1SGA-PLV-1C Text ID : ______ Accepted By : ______ Signature : ________

Ref No Last Reading : No Reading ** Delay Codes Legend ** W=Whse C=CrSp T=Tag TL=Tool P=Plan ** Record Time Daily ** Delays Step Job Scope MN DY Safety and Additional Information Emp No Date Hours Code/Hrs UNIT 1 "C" MILL, INSTALL (6 ea) BOILER 2 1 SAFETY: COAL FEED LINE RESTRICTORS IN SUPPLY 1- VERIFY YOUR CLEARANCE AND SAFE WORK PIPES. CONDITIONS FOR THIS JOB. _____ 2- SCAFFOLDING AND OR MAY BE REQUIRED TO SAFELY COMPLETE THIS JOB. COMMUNICATE WITH YOUR SUPERVISOR AS NEEDED FOR SPECIAL SCOPE: REQUIREMENTS. 1- INSTALL THE SET OF SIX RESTRICTORS, ONE EACH IN EACH OF THE BOILER COAL FEED 3- COMPLY WITH ALL COMPANY POLICY SUPPLY LINES. REGARDING SAFETY PROCEDURES, HOT WORK, SCAFFOLDING, TAGGING, RIGGING, AND PPE. 2- THE EXACT LOCATION TO BE DETERMINED BY *********** ENGINEERING (PHIL HAILES), AND MARKED. ************ 3- PREP COMPLETELY THE AREA TO BE CUT FOR ADDITIONAL INFORMATION: INSTALLATION OF THE RESTRICTOR. 1- THIS IS A HOT WORK PERMIT JOB! 4- FLUSH THE LINE completely TO WET DOWN AND REDUCE ANY POSSIBILITY OF FIRE OR 2- USE PROPER PRACTICES FOR FIRE WATCH. EXPLOSION. 3- PLEASE CLEAN UP AFTER YOURSELF. 5- USE PROPER LAYOUT METHODS TO ASSURE THAT THE CUT WILL BE EXACTLY PARALLEL WITH 4- PARTS ARE STAGED.

5- COMPLETE OTHER WORK AS DIRECTED BY YOUR

SUPERVISOR.

** IMPORTANT NOTICE **
YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST
ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY
JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS
CONCERNING THE WORK RULES, SAFETY CODES, OR
REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Page 1 Of 3

Failure Code:

Job Feedback/Historical Notes:

TEH PREFERRED SEALANT.

THE COAL PIPE AND MATCH MARK AS REQUIRED.

RESTRICTOR MOUNTING BRACKET, STITCH WELD AND SEAL WELD PER MFG. DIRECTIONS.

7- INSTALL RESTRICTOR VALVE ASSEMBLY INTO

THE MOUNTING BRACKET, USE GORTEX TAPE AS

6- POSITION AND TACK IN PLACE THE



7_0374

CREW: 47 WORK ORDER TYPE: MODIFICATIONS 02-60456-38 ISSUE DATE 01/06/11 Page 3 Of 3

** Work Order Parts List **								
:	Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	39408	CASKET MATERIAL TAPE	S 257250	08/14/03	FT	14	0	14